NTSB ID: DCA97MA017 Aircraft Registration Number: N265CA

Occurrence Date: 01/09/1997 Most Critical Injury: Fatal

Occurrence Type: Accident Investigated By: NTSB

Location/Time

Airport Proximity: Off Airport/Airstrip	1	m Landing Facility:		Direction Fro	m Airport
MONROE	MI	48161	1554	EST	
Nearest City/Place	State	Zip Code	Local Time	Time Zone	

Aircraft Information Summary

Aircraft Manufacturer	Model/Series	Type of Aircraft
Embraer	EMB-120RT	Airplane

Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On January 9, 1997, Comair flight 3272, an Embraer EMB-120RT, N265CA, crashed while being vectored for approach to runway 3R at Detroit Metropolitan Wayne County Airport. The flight was operated under Code of Federal Regulations (CFR) Part 135 and carried 26 passengers and 3 crew members. There were no survivors, and the airplane was destroyed by impact forces and a post crash fire. Instrument meteorological conditions prevailed at the time of the accident.

NTSB ID: DCA97MA017

Occurrence Date: 01/09/1997

FACINAL REPORT		Occurrence Bate. 01/09/1997										
AVIATION	Occurrence Type: Accident											
Landing Facility/Approach Inform	nation											
Airport Name		,	Airport ID:	Airport Eleva	tion	Run	way Used	Runway Lengt		th Run		ay Width
DETROIT METROPOLITAN DT				640 Ft.	640 Ft. MSL 3R				10000			
Runway Surface Type: Concrete												
Runway Surface Condition:												
Type Instrument Approach: ILS-locali	zer Only											
VFR Approach/Landing:												
Aircraft Information												
Aircraft Manufacturer				l/Series						Number		
Embraer			EMB	-120RT					1202	57		
Airworthiness Certificate(s): Transpor	t											
Landing Gear Type: Retractable - Tr	icycle											
Homebuilt Aircraft? No Nu	mber of Seats: 3	30	Certifie	ed Max Gross W	25353 LBS Number			er of Engines: 2		2		
Engine Type: Turbo Prop				Engine Manufacturer: Model/Series: P&W PW118					Rated Power: 1800 HP			
- Aircraft Inspection Information												
Type of Last Inspection			Date of Last Inspection Time Sir			Since Last Inspection			Airframe Total Time			
Continuous Airworthiness			12/1996	12/1996 89 Ho					ours 12752 Hours			52 Hours
- Emergency Locator Transmitter (ELT) Information											
ELT Installed? Yes	ELT Operate	ed?			ELT A	vided ir	n Locating Ac	cident S	Site?			
Owner/Operator Information												
Registered Aircraft Owner			Street	Address	ΓΗ ΜΔΙ	N STE	REET					
FIRST SECURITY BANK OF UTA	ιН,		City	79 SOUTH MAIN STREET City								Zip Code
			SALT LAKE CITY UT 84111								34111	
Operator of Aircraft			Street A	Address P.O.BOX	(75021	I						
COMAIR, INC.				City CINCNNATI							- 1	Zip Code 5275
Operator Does Business As: COMAIR AIRLINES				CINCNNATI OH 45275 Operator Designator Code: COMA								
- Type of U.S. Certificate(s) Held:												
Air Carrier Operating Certificate(s): Co	mmuter Air Ca	arrier; F	Flag Carrie	er/Domestic								
Operating Certificate: Operator Certificate:												
Regulation Flight Conducted Under: Part 135: Air Taxi & Commuter												
Type of Flight Operation Conducted: S	cheduled; Dor	nestic;	Passenge	er Only								
]	FACTU	JAL REPO	ORT - AVIATI	ON							Page 2

NTSB ID: DCA97MA017

Occurrence Date: 01/09/1997

AVIATI	QN		Occurrence Type: Accident										
First Pilot Information													
Name					City					State	e C	Date of Birth	Age
On File					On File)				On F	File	On File	42
Sex: M Seat Occupied	: Left	Prir	ncipal Profes	sion: Civilia	n Pilot				Cer	tificate	Numbe	er: On File	
Certificate(s): Airline Transport; Commercial													
Airplane Rating(s): Multi-engine Land; Single-engine Land													
Rotorcraft/Glider/LTA: Heli	copter												
Instrument Rating(s): Heli	copter												
Instructor Rating(s): Non	е												
Type Rating/Endorsement for	or Accident/In	cident Aircra	ft? Yes			С	urrent E	Biennial	Flight R	eview'	?		
Medical Cert.: Class 1	Medica	al Cert. Status	: Valid Me	dicalno wa	aivers/lir	m.		Da	ate of La	ıst Me	dical Ex	am: 08/1996	
- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night	ŧ	Actual	Instrument	ent Simulated		otorcraft	Glider	Lighter Than Air
Total Time	5329	2302											
Pilot In Command(PIC)	3400	1097			<u> </u>			_		\perp			
Instructor					-			_		+			
Last 90 Days	234							-		+			
Last 30 Days Last 24 Hours	85 2					\dashv		-		+		+	
Seatbelt Used?	<u> </u>	lder Harness	Llead?		<u> </u>	Fovice	l ology Pe	rforme	d? Voc		Sec	I cond Pilot? Ye	
Gealbeit Osed:	31100	ilder Harriess	Useu:			OXICO	nogy i c	,110111100	u: 162		1000	cond i not: Te	:5
Flight Plan/Itinerary													
Type of Flight Plan Filed: IF	R												
Departure Point						State		Airport Identifier Depart			Depart	rture Time Time Zone	
CINCINNATI						ОН		CVG			1451		EST
Destination						State		Airport	Identifie	r			
DETROIT MI DTW													
Type of Clearance: IFR													
Type of Airspace: Class	В												
Weather Information													
Source of Briefing: Company													
Method of Briefing:													
FACTUAL REPORT - AVIATION Page 3													

NTSB ID: DCA97MA017

Occurrence Date: 01/09/1997

Occurrence Type: Accident

	ETYBOR			currence	Type:	Accider	1τ							
Weather	Information													
WOF ID	Observation Time	Time Zone	WOF	Elevation	1	WOF Distance From Accident Site					Direction Fron	n Accident Si	te	
DTW	2054	EST		640 Ft. M	1SL				19 NM		20 Deg. Mag.			
Sky/Lowes	st Cloud Condition: Thin	Broken					600 Ft. AC	GL	Condition o	Condition of Light: Day				
Lowest Ce	eiling: Broken		6	600 Ft. A	GL	Visib	oility:	0.75	SM	Alti	meter:	29.00	"Hg	
Temperatu	ıre: -2 °C	Dew Point:		3 °C	Wind I	Direction:	: 70			Dei	ensity Altitude: Ft.			
Wind Spee	ed: 5	Gusts:			Weath	er Condt	tions at Acci	ident S	ite: Instrume	ent C	Conditions			
Visibility (R	RVR): Ft.	Visibility	y (RVV)		SM	Intensit	ty of Precipit	tation:						
Restriction	ns to Visibility:													
Type of Pre	Type of Precipitation: Snow													
Accident	Information													
Aircraft Dar	mage: Destroyed		Airc	raft Fire:	Grour	nd			Aircraft Exp	losio	n None			
Classificati	ion: U.S. Registered/U	.S. Soil												
- Injury Su	mmary Matrix	Fatal	Serious	Minor		None	TOTAL							
First Pi	ilot	1					1	1						
Second	d Pilot	1					1	1						
Studen	nt Pilot				\top			1						
Flight I	nstructor							1						
Check	Pilot							1						
Flight E	Engineer				\top			1						
Cabin /	Attendants	1			\top		1	1						
Other C	Crew							7						
Passen	ngers	26					26	5						
- TOTAL A	ABOARD -	29					29	5						
Other C	Ground	0	0		0		0	5						
- GRAND	O TOTAL -	29	0		0		29	<u> </u>						

National Transportation Safety B	Soard
----------------------------------	-------

FACTUAL REPORT AVIATION

NTSB ID: DCA97MA017

Occurrence Date: 01/09/1997

Occurrence Type: Accident

PETYBOR	Occurrence Type. Accident	
Administrative Information		
Investigator-In-Charge (IIC)		
RICHARD G. RODRIGUEZ		
Additional Persons Participating in This Accident/Incide	ent Investigation:	
ROBERT L HENLEY		